



















SW10





SW7







T20




















T20











SW23








2. 	2.1 4x15 	2.3 	2.4 	2.5  2x/4x/6x  2x/4x/6x 3x13 SW7
2.6 	2.11 	2.13 4x20 	2.14   6x24	2.15 2x22 
2.16 	2.18   ≥ 140 cm 	2.20 	4. 	
3. 	3.5  4x15	3.10 2x/4x/6x  4x19	3.11  	













2.




2.1








4x15



2.2





2.3




2.4

2.4



2.5




4x/6x




**4x/6x
3x13**





1






2





A black and white line drawing of a power cord. The cord is coiled in a large loop. At the top right, there is a three-pronged electrical plug. At the bottom right, there is a two-pronged electrical plug. The cord has a textured, braided appearance.





2.11




2.12



2.12




2.13




① 4x20




② 4x20



2.14





6x24





2.15

4x22




2




2.16




1





2




3




3




2.17




2.18




2.19





2.20




3.




3.1




3.2




3.3






3.4




3.5







3.9





3.10






**2x/4x/6x
4x19**



3.11



4.



Miele & Cie. KG
Carl-Miele-Straße 29
33332 Gütersloh
Germany
Tel.: +49 5241 89-0
Internet: www.miele.com

