


Bissell®

CROSSWAVE X7 PLUS

3400, 3401, 3479 SERIES





.....3



.....4



.....5



.....6










.....7









.....8



.....9


























	⚡ [] [] [] ✓
100% - 70%	[] [] []
69% - 40%	[] [] []
39% - 10%	[] [] []
> 9% - 1%	[] [] []
0%	[] [] []


















MASS POWER
S030-1B297100HE



























24



25



26





©2022 BISSELL Inc. All rights reserved.
Part Number 1629362 11/21 RevA
global.BISSELL.com